Dehydrated Culture Media Bases / Media Supplements

Material Safety Data Sheet

Code No.	Product	Herellea Agar			
	: Chemical Identification	DM1505			
Section 1	Code No.				
	Name of the Product	: DM1505			
		: Herellea Agar	N.+ 1+d		
	Produced by	: Central Drug House P			
	Address		Darya Ganj, New Delhi (INDIA)		
	Tel. No.	: 00 91 11 49404040			
Section 2	Composition Ingredients	Grams/Litre	Ingredients	Grams/Litre	
	Casein enzymic hydrolysate	15.00	Papaic digest of soyabean meal	5.00	
	Sodium chloride	5.00	Lactose	10.00	
	Maltose	10.00	*Bile salts mixture	1.25	
	Bromo cresol purple	0.02	Agar	16.00	
	Final pH (at 25°C)	6.8±0.2		20.00	
		0.8±0.2			
	* Irritant material				
	Bile salts mixture				
	S:22-24/25				
Section 3	Hazards Identification				
\wedge	Hazard : This symbol designate	es substances which may hav	e an irritant effect on skin, eyes and resp	piratory organs.	
\checkmark	Caution : Do not breathe vapours and avoid contact with skin and eyes.				
Section 4			•		
Section 4	First - Aid Measures In case of swallowing, wash out mouth with water provided person is conscious. In case of skin contact,flush with copious				
	_			lact, hush with copious	
	amounts of water for at least 2		•		
			mes difficult, call physician. In case of co		
	copious amounts of water for at least 15 minutes. Assure adequate washing by separating the eyelids with fingers. In serious				
	conditions, call a physician, show the container or label.				
Section 5	Fire Fighting Measures				
	Extinguishing Media. Water spray.				
	Extinguisining Media. Water sp	iray.			
			Special fire-fighting procedures. Wear so	elfcontained breathing	
		oowder or appropriate foam.		elfcontained breathing	
Section 6	Carbon dioxide, dry chemical p	bowder or appropriate foam. hing to prevent contact with		elfcontained breathing	
Section 6	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur	bowder or appropriate foam. hing to prevent contact with s es			
Section 6	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe	bowder or appropriate foam. hing to prevent contact with s es ety goggles, rubber boots and	skin and eyes.		
	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve	bowder or appropriate foam. hing to prevent contact with s es ety goggles, rubber boots and	skin and eyes. I heavy rubber gloves. Sweep up, place in		
	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage	bowder or appropriate foam. hing to prevent contact with s es ety goggles, rubber boots and entilate area and wash spill si	skin and eyes. I heavy rubber gloves. Sweep up, place in		
	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8	bowder or appropriate foam. hing to prevent contact with s es esty goggles, rubber boots and entilate area and wash spill si 3	skin and eyes. I heavy rubber gloves. Sweep up, place in		
Section 7	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si g	skin and eyes. I heavy rubber gloves. Sweep up, place in		
Section 7	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si g	skin and eyes. I heavy rubber gloves. Sweep up, place in		
Section 7	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si al Protection	skin and eyes. I heavy rubber gloves. Sweep up, place in	n a bag and hold for waste	
Section 7	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required.	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si all Protection h-approved respirator, chemi	skin and eyes. I heavy rubber gloves. Sweep up, place in ite after material pickup is complete.	n a bag and hold for waste	
Section 7 Section 8	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si all Protection h-approved respirator, chemi	skin and eyes. I heavy rubber gloves. Sweep up, place in ite after material pickup is complete.	n a bag and hold for waste	
Section 7 Section 8	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi perties	skin and eyes. I heavy rubber gloves. Sweep up, place in ite after material pickup is complete.	n a bag and hold for waste	
Section 7 Section 8	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required.	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi perties	skin and eyes. I heavy rubber gloves. Sweep up, place in ite after material pickup is complete.	n a bag and hold for waste	
Section 7 Section 8 Section 9	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi perties	skin and eyes. I heavy rubber gloves. Sweep up, place in ite after material pickup is complete.	n a bag and hold for waste	
Section 7 Section 8 Section 9	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si and Protection h-approved respirator, chemi perties bowder.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe	n a bag and hold for waste	
Section 7 Section 8 Section 9	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si and Protection h-approved respirator, chemi berties bowder. tored as per the conditions sp	skin and eyes. I heavy rubber gloves. Sweep up, place in ite after material pickup is complete.	n a bag and hold for waste	
Section 7 Section 8 Section 9	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4	bowder or appropriate foam. hing to prevent contact with sets es esty goggles, rubber boots and entilate area and wash spill si anal Protection anapproved respirator, chemi berties bowder. tored as per the conditions sp 5°C.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe	n a bag and hold for waste	
Section 7 Section 8 Section 9	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si anal Protection anapproved respirator, chemi perties bowder. tored as per the conditions sp 15°C. light.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe	n a bag and hold for waste	
Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will	bowder or appropriate foam. hing to prevent contact with set es esty goggles, rubber boots and entilate area and wash spill si anal Protection anapproved respirator, chemi perties bowder. tored as per the conditions sp 15°C. light.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe	n a bag and hold for waste	
Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will Toxicological Information	bowder or appropriate foam. hing to prevent contact with a es esty goggles, rubber boots and entilate area and wash spill si and Protection an-approved respirator, chemi berties bowder. tored as per the conditions sp 15°C. light. not occur.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe	n a bag and hold for waste	
Section 6 Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will Toxicological Information Acute Effects : May be harmfu	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi berties bowder. tored as per the conditions sp 15°C. light. not occur. I if swallowed.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe pecified under storage of Section No. 7.P	n a bag and hold for waste r protective clothing.	
Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will Toxicological Information Acute Effects : May be harmfu	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi berties bowder. tored as per the conditions sp 15°C. light. not occur. I if swallowed.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe	n a bag and hold for waste	
Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will Toxicological Information Acute Effects : May be harmfu	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi berties bowder. tored as per the conditions sp 15°C. light. not occur. I if swallowed.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe pecified under storage of Section No. 7.P	n a bag and hold for waste r protective clothing.	
Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will Toxicological Information Acute Effects : May be harmfu Exposure can cause : Stomach	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi berties bowder. tored as per the conditions sp 15°C. light. not occur. I if swallowed.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe pecified under storage of Section No. 7.P	n a bag and hold for waste	
Section 7 Section 8 Section 9 Section 10	Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measur Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section & Storage - Store below 30°C Exposure Controls / Person Wear appropriate Niosh/Msha Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Yellow Stability and Reactivity Stability : Product is stable if st potency/performance above 4 Conditions to avoid : Heat and Hazardous polymerization will Toxicological Information Acute Effects : May be harmfu Exposure can cause : Stomach certain sensitive individuals.	bowder or appropriate foam. hing to prevent contact with set es ety goggles, rubber boots and entilate area and wash spill si al Protection h-approved respirator, chemi berties bowder. tored as per the conditions sp 15°C. light. not occur. I if swallowed.	skin and eyes. I heavy rubber gloves. Sweep up, place in te after material pickup is complete. cal-resistant gloves, safety goggles, othe pecified under storage of Section No. 7.P	n a bag and hold for waste	

Central Drug House (P) Ltd. Corp. Office : 7/28, Vardaan House, Ansari Road, Daryaganj, New Delhi-110002 (INDIA) Phone : +91-11- 49404040 (100 Lines) Fax : +91-11- 49404050 E-mail : sales@cdhfinechemical.com Website : www.cdhfinechemical.com



Dehydrated Culture Media Bases / Media Supplements

	On completion of work all used or unusable preparations of this product and derivatives thereof are to be disposed off by autoclaving and/or by incineration. Dispose off waste in accordance with all applicable Federal, State and local laws.			
Section 14	Transport Information			
	UN No. : Not applicable.			
Section 15	Regulatory Information			
	Safety Phrases : Do not breathe dust			
	Safety Phrases : Avoid contact with skin or eyes			
\wedge	Significance of signs : This symbol designates substances which may have an irritant effect on skin, eyes and respiratory			
Skin irritation	organs.			
Section 16	Other Information			
	The information contained in this data sheet represents the best information currently available to us. However, no warranty is made with respect to its completeness and we assume no liability resulting from its use. The information is offered solely for user's obligation to investigate and determine the suitability of the information for their particular purpose.			