Dehydrated Culture Media Bases / Media Supplements

Material Safety Data Sheet

	Product		EMB Agar Base				
Code No.			DM 1301				
Section 1	: Chemical Identification		DN4 1201				
	Code No. Name of the Product		DM 1301				
			EMB Agar Base	v+ 1+d			
	Produced by Address		Central Drug House P				
	Tel. No.		7/28 Vardaan House, Darya Ganj, New Delhi (INDIA) 00 91 11 49404040				
Section 2	Chemical Identification Ingre	edients		Ingredients	Grams/Litre		
	Peptic digest of animal tissue		10.00	Dipotassium phosphate	2.00		
	Eosin - Y		0.40	*Methylene blue	0.065		
	Agar		15.00				
	Final pH (at 25°C)		7.3±0.2				
	* Harmful material						
Skin Irritation	Methylene blue						
	CAS No. : 7220-79-3						
	R : 22 S : 22-24/25						
	RTECS : SO 5600000						
Section 3	Hazards Identification						
Skin irritation	Hazard : Inhalation and ingestion of, or skin penetration by these substances is harmful to one.s health. Non-recurring,						
	recurring or lengthy exposure to these substances may result in irreversible damage.						
	Caution : Avoid contact with the human body, including inhalation of the vapours and in cases of malaise consult a doctor.						
Section 4							
Section 4	First - Aid Measures						
	In case of swallowing, wash out mouth with water provided person is conscious. In case of skin contact, flush with copious amounts of water for at least 15 minutes. Remove contaminated clothing and shoes. In case of inhalation,						
	remove to fresh air. If breathing becomes difficult, call physician. In case of contact with eyes, wash with copious						
	amounts of water for at least 15 minutes. Assure adequate washing by separating the eyelids with fingers. In serious						
	conditions, call a physician, show the container or label.						
Section 5	Fire Fighting Measures						
	Extinguishing Media. Water spray. Carbon dioxide, dry chemical powder or appropriate foam. Special fire-fighting						
	procedures. Wear selfcontained breathing apparatus and protective clothing to prevent contact with skin and eyes.						
Section 6		Accidental Release Measures					
Section 6	•	res			with skin and eyes.		
Section 6	Accidental Release Measur Wear respirator, chemical saf	ety gog		d heavy rubber gloves. Sweep up, plac	e in a bag and hold for		
	Accidental Release Measur Wear respirator, chemical saf	ety gog		· · · · · · · · · · · · · · · · · · ·	e in a bag and hold for		
	Accidental Release Measur Wear respirator, chemical saf	ety gog		d heavy rubber gloves. Sweep up, plac	e in a bag and hold for		
	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising d	ety gog		d heavy rubber gloves. Sweep up, plac	e in a bag and hold for		
	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C	ety gog dust. V	entilate area and was	d heavy rubber gloves. Sweep up, plac	e in a bag and hold for		
Section 6 Section 7 Section 8	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8	ety gog dust. V	entilate area and was	d heavy rubber gloves. Sweep up, plac	e in a bag and hold for		
Section 7	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH	ety gog dust. V nal Pro	entilate area and was	d heavy rubber gloves. Sweep up, plac	e in a bag and hold for plete.		
Section 7	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required.	ety gog dust. V nal Pro	entilate area and was otection roved respirator, che	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com	e in a bag and hold for plete.		
Section 7	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH	ety gog dust. V nal Pro	entilate area and was otection roved respirator, che	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com	e in a bag and hold for plete.		
Section 7 Section 8	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p	ety gog dust. V nal Pro HA-app perties	entilate area and was Detection roved respirator, che	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com	e in a bag and hold for plete.		
Section 7 Section 8 Section 9	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSF Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous p Colour : Pink to purple	ety gog dust. V nal Pro HA-app perties	entilate area and was Detection roved respirator, che	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com	e in a bag and hold for plete.		
Section 7 Section 8 Section 9	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p	ety gog dust. V nal Pro HA-app perties	entilate area and was Detection roved respirator, che	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com	e in a bag and hold for plete.		
Section 7 Section 8 Section 9	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s	ety gog dust. V nal Pro HA-app perties bowder	entilate area and was Detection roved respirator, che s	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com	e in a bag and hold for plete.		
Section 7 Section 8 Section 9	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above of	ety gog dust. V nal Pro HA-app perties bowder	entilate area and was Detection roved respirator, che s	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, o	e in a bag and hold for plete.		
Section 7 Section 8 Section 9	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above Conditions to avoid : Heat and	ety gog dust. V nal Pro HA-app perties bowder stored a 45°C. d light.	entilate area and was Detection roved respirator, che s as per the conditions	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, o	e in a bag and hold for plete.		
Section 7 Section 8 Section 9 Section 10	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above Conditions to avoid : Heat and Hazardous polymerization wil	ety gog dust. V nal Pro HA-app perties bowder stored a 45°C. d light.	entilate area and was Detection roved respirator, che s as per the conditions	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, o	e in a bag and hold for plete.		
Section 7 Section 8 Section 9 Section 10	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above of Conditions to avoid : Heat and Hazardous polymerization wil	ety gog dust. V hal Pro HA-app perties bowder stored a 45°C. d light. I not o	entilate area and was ptection roved respirator, che s as per the conditions ccur.	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, o	e in a bag and hold for plete.		
Section 7 Section 8 Section 9 Section 10	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above Conditions to avoid : Heat and Hazardous polymerization wil Toxicological Information Acute Effects : May be harmfu	ety gog dust. V hal Pro HA-app perties bowder stored a 45°C. d light. l not ou	entilate area and was ptection roved respirator, che s as per the conditions ccur. allowed.	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, c	e in a bag and hold for plete. other protective clothing 7. Product loses its		
Section 7 Section 8 Section 9 Section 10	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above Conditions to avoid : Heat and Hazardous polymerization wil Toxicological Information Acute Effects : May be harmfu Exposure can cause : Stomach	ety gog dust. V hal Pro HA-app perties bowder stored a 45°C. d light. l not ou	entilate area and was ptection roved respirator, che s as per the conditions ccur. allowed.	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, o	e in a bag and hold for plete. other protective clothing 7. Product loses its		
Section 7 Section 8	Accidental Release Measur Wear respirator, chemical saf waste disposal. Avoid raising of Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSh/MSH Mechanical exhaust required. Physical and Chemical Pro Appearance : Homogeneous p Colour : Pink to purple Stability and Reactivity Stability : Product is stable if s potency/performance above Conditions to avoid : Heat and Hazardous polymerization wil Toxicological Information Acute Effects : May be harmfu	ety gog dust. V nal Pro HA-app perties bowder stored a 45°C. d light. l not on ul if swa pains,	entilate area and was ptection roved respirator, che s as per the conditions ccur. allowed. vomiting, diarrhoea.	d heavy rubber gloves. Sweep up, plac h spill site after material pickup is com mical-resistant gloves, safety goggles, o specified under storage of Section No.	e in a bag and hold for plete. other protective clothing 7. Product loses its		





	Data not available				
Section 13	Disposal Considerations				
	On completion of work all used or unusable preparations of this product and derivatives thereof are to be disposed off by autoclaving and/or by incineration. Dispose off waste in accordance with all applicable Federal, State and local laws.				
Section 14	Transport Information				
	UN No. : Not applicable.				
Section 15	Regulatory Information				
	Risk Phrases : Harmful if swallowed				
	Safety Phrases: Do not breathe dust				
	Safety Phrases : Avoid contact with skin or eyes				
Skin irritation	Significance of signs : Inhalation and ingestion of, or skin penetration by these substances is harmful to one.s health. Non-recurring, recurring or lengthy exposure to these substances may result in irreversible damage.				
Section 16	Other Information				
	The information contained in this data sheet represents the best information currently available to us. However, no warranty is made with respect to its completeness and we assume no liability resulting from its use. The information is offered solely for user.s obligation to investigate and determine the suitability of the information for their particular purpose.				