



Product Specification

cdhfinechemical.com

PYRIDINE "DRY" AR

PRODUCT CODE 620355

SYNONYMS --


C.I. NO. --

CASR NO. 110-86-1

ATOMIC OR MOLECULAR FORMULA C₅H₅N

ATOMIC OR MOLECULAR WEIGHT 79.10

PROPERTIES --



PARAMETER LIMIT

Description	A clear liquid, not more than 10 Hazen units in colour, with a characteristic odour.
Solubility	Miscible with water & methanol forming clear and colourless solution.
Minimum Assay	99.5%
Wt. per ml at 20 ^o C	0.982-0.983 g
Boiling Range	114 ^o -116 ^o C
Refractive Index (n) 20 D	1.509-1.510

MAXIMUM LIMIT OF IMPURITIES

Water insoluble matter	Passes test.
Water	0.05%
Non-volatile matter	0.002%
Chloride (Cl)	0.0005%
Ammonia (NH ₃)	0.002%
Copper (Cu)	0.0002%
Iron (Fe)	0.0002%
Lead (Pb)	0.0001%
Substances reducing permanganate (O)	0.0008%

Note(s) : Assay (if applicable) method mentioned.

WARNING

HAZARD STATEMENTS : May cause respiratory irritation. Flammable liquid and vapour. Harmful if swallowed. Causes mild skin irritation. Causes eye irritation.

PRECAUTIONARY STATEMENTS :

Prevention : Ground/bond container and receiving equipment. Use only nonsparking tools. Take precautionary Measures against static discharge. Wash hands thoroughly after handling. Do not eat, drink or smoke when using this product. Keep away from heat/sparks/open flame - No smoking. Keep container tightly closed. Use explosion-proof electrical/ventilating/lighting/equipment. Wear protective gloves and eye/face protection.

Response : If eye irritation persists, get medical advice/attention. If skin irritation occurs, seek medical advice/attention. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Specific treatment: refer to Label or MSDS. If on skin or hair: remove/take off immediately all contaminated clothing. Rinse with water/shower. In case of fire, use foam for extinction.

IMDG Code : --

UN No. : --

IATA : --

Disposal : Allow to evaporate in safe open area (applicable for small quantities). The chemical should be burnt in a chemical incinerator equipped with burner and scrubber. If the volumes are larger than 500ml and no incinerator and site of evaporation is not available then transfer the waste chemical to waste solvent drum for collection by specialist disposal company.

Hazard Pictogram(s) :-



Product Specification

cdhfinechemical.com



GHS02



GHS07

Replace Date 16-Dec-2020