



## **Product Specification**

cdhfinechemical.com

## POTASSIUM HYDROXIDE IN METHANOL 0.5 M (0.5N) ALCOHOLIC CTITRINORM VOLUMETRIC SOLUTION

PRODUCT CODE	877850
SYNONYMS	<b></b>
C.I. NO.	<del></del>
CASR NO.	<del></del>
ATOMIC OR MOLECULAR FORMULA	<del></del>
ATOMIC OR MOLECULAR WEIGHT	
PROPERTIES	<b></b>
PARAMETER	LIMIT
Description	Clear Colourless solution.
Solubility	Miscible with water.

Note(s): Assay (if applicable) method mentioned.

DANGER

HAZARD STATMENTS: Flammable liquid and vapour. Toxic if inhaled. Harmfuin contact with skin. Harmful if swallowed. UN No. : 3286

May cause allergic or asthmatic symptoms or breathing difficulties if inhaled. May cause allergic skin reaction. May be corrosive to metals. Causes severe skin burns and eye damage.

## PRECAUTIONARY STATEMENTS:

Normality

Prevention: Do not breathe dust/fume/gas/mist/vapours/spray. Use only outdoors or in a well ventilated area. Avoid breathing dust/fume/gas/mist/vapours/spray. Do not eat, drink or smoke when using this product. Wash hands thoroughly after handling. Wear protective gloves/clothing.Do not breathe dust or mist.In case of inadequate ventilation wear respiratory protection. Contaminated clothing should not be allowed out of the workplace. Wear protective gloves/clothing and eye/face protection. Wash thoroughly after handling. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment Take precautionary measures against static discharge Use only non-sparking tools. Keep away from heat/sparks/open flame - No smoking. Keep container tightly closed. Wear protective gloves and eye/face protection.

0.49-0.51N

Response: In case of fire, use alcohol-type foam for extinction. Wash contaminated clothing before reuse. IF INHALED: Remove to fresh air and keep at rest in a position comfortable for breathing. If on skin or hair: remove/take off immediately all contaminated clothing. Rinse with water/shower. If experiencing respiratory symptoms call a POISON CENTER or doctor/physician. Absorb spillage to prevent material damage. If skin irritation or rash occurs, seek medicaadvice/attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF INHALED: If breathingis difficult, remove to fresh air and keep at rest in a position comfortable for breathing. IF ON SKIN: Gently wash with plenty of soap and water. Immediately call a POISON CENTER or doctor/physician. Call a POISON CENTER or doctor/physician if you feel unwell. Specific treatment: refer to Label or

**Disposal:** Add a little at a time (2 to 5g) to a large volume of water. After the reaction or solution is complete, allow it to run to normal waste, diluting with large amount of water. Any sand used to cover spillage should be thoroughly washed with water before disposal as normal waste.

## Hazard pictogram(s):

MSDS.









Replace Date 29-Nov.-2018