



## **Product Specification**

cdhfinechemical.com

	PROPYLENE OXIDE AR	
PRODUCT CODE	619505	
SYNONYMS		
C.I. NO.		
CASR NO.	(75-56-9)	_CH₃
ATOMIC OR MOLECULAR FORMULA	C₃H₀O	
ATOMIC OR MOLECULAR WEIGHT	58.08	$\setminus$ /
PROPERTIES		0
PARAMETER	LIMIT	
Description	A clear colourless liquid.	
Solubility	Miscible with alcohol and ether.	
Minimum assay	99.5%	
Wt. per ml at 25°C	About 0.83 g	
Refractive index (n) <u>20</u>	1.366	
D		
MAXIMUM LIMIT OF IMPURITIES		
Water	0.1%	
Residue on Evapn.	0.005%	
Aluminum (Al)	0.00005%	
Barium (Ba)	0.00001%	
Bismuth (Bi)	0.00001%	
Calcium (Ca)	0.00005%	
Cadmium (Cd)	0.000005%	
Cobalt (Co)	0.000002%	
Chromium (Cr)	0.000002%	
Copper (Cu)	0.000002%	
Iron (Fe)	0.00001%	
Potassium (K)	0.00005%	
Lithium (Li)	0.00001%	
Magnesium (Mg)	0.00001%	
Manganese (Mn)	0.00002%	
Molybdate (Mo)	0.00001%	
Sodium (Na)	0.00005%	
Nickel (Ni)	0.000002%	
Lead (Pb)	0.00001%	
Strontium (Sr)	0.00001%	
Zinc (Zn)	0.00001%	



## **Product Specification**

cdhfinechemical.com

Note(s) : Assay (if applicable) method mentioned.		
DANGER		9 :
HAZARD STATEMENTS :May cause respiratory irritation. May cause drowsiness or dizziness. Highly flammable liquid and vapour. May be harmful if swallowed. May be fatal if swallowed and enters airways. Causes mild skin irritation. Causes serious eye irritation. Harmful to aquatic life.	UN No. IATA	:
PRECAUTIONARY STATEMENTS : Prevention : Keep away from heat/sparks/open flames/hot surfaces No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Avoid breathing dust/fume/gas/mist/vapours/spray. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Wear protective gloves/protective clothing/eye protection/face protection. Response :IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Call a POISON CENTER or doctor/physician. If eye irritation persists: Get medical advice/attention. Disposal :Allow to evaporate in safe open area (applicable for small quantities). The chemical should be burnt in a chemical incinerator equipped with burner and scrubber. If the volumes are larger than 500ml and no incinerator and site of evaporation is not available then transfer the waste chemical to waste solvent drum for collection by specialist disposal company.		
Disposal :	7	
Hazard Pictogram(s) :		