



Product Specification

cdhfinechemical.com

SODIUM LAURYL SULPHATE AR FOR SDS ELECTROPHORESIS		
PRODUCT CODE	644595	
SYNONYMS		
С.І. NO.		
CASR NO.	(151-21-3)	0
ATOMIC OR MOLECULAR FORMULA	C ₁₂ H ₂₅ NaO₄S	
ATOMIC OR MOLECULAR WEIGHT	288.38	$CH_3(CH_2)_{10}CH_2O-S-ONa$
PROPERTIES	Slight characteristic odour , Hygroscopic.	0
PARAMETER	LIMIT	
Description	White powder.	
Solubility	0.1M solution in water is clear to nearly clear and colo	ourless
Minimum assay (After drying, two phase titration.)	99.0%	
Maximum absorbance	0.1	
(3% soln in water at 220 - 350nm) MAXIMUM LIMIT OF IMPURITIES		
Loss on drying (at 110°C)	1.00/	
Water insoluble matter	1.0%	
	0.003%	
Chloride (Cl)	0.02%	
Phosphate	0.0001%	
Copper (Cu)	0.0001%	
Iron (Fe)	0.0001%	
Lead (Pb)	0.0002%	
Note(s): Assay (if applicable) method mentioned.		
	sed to air. May be corrosive to metals. Harmful if swall	
severe skin burns and eye damage. Causes serious e PRECAUTIONARY STATEMENTS	-	UN No. : 1325 IATA : 4.1
	s/hot surfaces No smoking. Do not allow contact with s/ mist/ vapours/ spray. Wash thoroughly after handl	
	ctive gloves/protective clothing/eye protection/face pro	
Response: IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. IF SWALLOWED: Rinse mouth. Do		
NOT induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with		
water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES:		
Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. Rinse mouth. Brush off loose particles from skin. Immerse in cool		
water/wrap in wet bandages. Wash contaminated clothing before reuse. Absorb spillage to prevent material damage.		
Disposal: Dissolve the chemical in dilute acid and neutralize the excess acid with sodium carbonate and run to the normal		
waste with large amount of water . Any sand used to cover spillage should be thoroughly washed with water beforedisposal		
as normal waste. Alternatively the neutralized soluti	on can be put in a container and disposed off.	
Disposal : Dissolve the chemical in dilute acid and ne	utralize the excess acid with sodium carbonate and run	to the normal waste with large amount
	horoughly washed with water beforedisposal as norma	
solution can be put in a container and disposed off.		
Hazard pictogram(s) :		
	$\nabla \vee \nabla$	
Replace Date 19-June-2018	GHS02 GHS05 GHS07	

Replace Date 19-June-2018