Material Safety Data Sheet



| Name of the Product | | Pseudomonas Agar (For Pyocyanin) | | | |
|--|--|--|---|---|--|
| Code No. | | DM 1119 | | | |
| Section 1 | : Chemical Identification | 514446 | | | |
| | Code No. : | DM 1119 | | | |
| | | Name of the Product : Pseudomonas Agar (For Pyocyanin) | | | |
| | Produced by : Address : | Central Drug House Pvt. Ltd. 7/28 Vardaan House, Darya Ganj, New Delhi (INDIA) 00 91 11 49404040 | | | |
| | Tel. No. | | | | |
| | | | | | |
| Section 2 | Composition Ingredients | Grams/Litre | Ingredients | Grams/Litre | |
| | Peptic digest of animal tissue | 20.00 | Potassium sulphate | 10.00 | |
| | *Magnesium chloride | 1.40 | Agar | 15.00 | |
| | Final pH (at 25°C) | 7.0 ± 0.2 | | | |
| | * Irritant material | | | | |
| | Information on Ingredients | | | | |
| | Magnesium chloride | | | | |
| | CAS No. : 7786-30-3 | | | | |
| | R : 36/37/38 S : 26-36 | 5 | | | |
| | RTECS : OM 2800000 | | | | |
| Section 3 | Hazards Identification | | | | |
| | Hazard : This symbol designates substances which may have an irritant effect on skin, eyes and respiratory organs. | | | | |
| | Caution : Do not breathe vapours and avoid contact with skin and eyes. | | | | |
| Section 4 | First - Aid Measures | | | | |
| | In case of swallowing, wash out mouth with water provided person is conscious. In case of skin contact, flush with copiou | | | | |
| | amounts of water for at least 15 minutes. Remove contaminated clothing and shoes. In case of inhalation, remove to | | | | |
| | fresh air. If breathing becomes difficult, call physician. In case of contact with eyes, wash with copious amounts of water | | | | |
| | for at least 15 minutes. Assure adequate washing by separating the eyelids with fingers. In serious conditions, call a | | | | |
| | physician, show the container or la | abel. | | | |
| | | | | | |
| Section 5 | Fire Fighting Measures | | | | |
| Section 5 | Extinguishing Media. Water spray. | | | | |
| Section 5 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow | der or appropriate foa | | es. Wear selfcontained breathing | |
| | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing | der or appropriate foa | | es. Wear selfcontained breathing | |
| | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures | der or appropriate foa to prevent contact w | ith skin and eyes. | · · · · · · · · · · · · · · · · · · · | |
| Section 5 Section 6 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g | der or appropriate foa to prevent contact w goggles, rubber boots | ith skin and eyes. and heavy rubber gloves. Sweep | up, place in a bag and hold for | |
| Section 6 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. | der or appropriate foa to prevent contact w goggles, rubber boots | ith skin and eyes. and heavy rubber gloves. Sweep | up, place in a bag and hold for | |
| Section 6 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage | der or appropriate foa to prevent contact w goggles, rubber boots | ith skin and eyes. and heavy rubber gloves. Sweep | up, place in a bag and hold for | |
| Section 6 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 | der or appropriate foa to prevent contact w goggles, rubber boots | ith skin and eyes. and heavy rubber gloves. Sweep | up, place in a bag and hold for | |
| Section 6 Section 7 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C | der or appropriate foa to prevent contact w goggles, rubber boots . Ventilate area and w | ith skin and eyes. and heavy rubber gloves. Sweep | up, place in a bag and hold for | |
| Section 6 Section 7 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku | up, place in a bag and hold for p is complete. | |
| Section 6 Section 7 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku | up, place in a bag and hold for p is complete. | |
| Section 6 Section 7 Section 8 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku | up, place in a bag and hold for p is complete. | |
| | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku | up, place in a bag and hold for p is complete. | |
| Section 6 Section 7 Section 8 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous powo | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku | up, place in a bag and hold for p is complete. | |
| Section 6 Section 7 Section 8 Section 9 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous power Colour : Cream to yellow | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku | up, place in a bag and hold for p is complete. | |
| Section 6 Section 7 Section 8 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous pow Colour : Cream to yellow Stability and Reactivity | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous pow Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the conditior | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous powe Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the conditior | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous pow Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C Conditions to avoid : Heat and light | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the conditior | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 Section 10 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous powc Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C Conditions to avoid : Heat and ligh Hazardous polymerization will not | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the conditior | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 Section 10 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous pow Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C Conditions to avoid : Heat and ligh Hazardous polymerization will not | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the conditior t. coccur. | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 Section 10 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous powe Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C Conditions to avoid : Heat and ligh Hazardous polymerization will not Toxicological Information Acute Effects : May be harmful if s | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the condition | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 Section 10 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous pow Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C Conditions to avoid : Heat and ligh Hazardous polymerization will not | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the condition | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |
| Section 6 Section 7 Section 8 Section 9 | Extinguishing Media. Water spray. Carbon dioxide, dry chemical pow apparatus and protective clothing Accidental Release Measures Wear respirator, chemical safety g waste disposal. Avoid raising dust. Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Personal F Wear appropriate NIOSH/MSHA-a Mechanical exhaust required. Physical and Chemical Propert Appearance : Homogeneous pow Colour : Cream to yellow Stability and Reactivity Stability : Product is stable if store potency/performance above 45°C Conditions to avoid : Heat and ligh Hazardous polymerization will not Toxicological Information Acute Effects : May be harmful if s Exposure can cause : Stomach pain | der or appropriate for to prevent contact w goggles, rubber boots Ventilate area and w Protection pproved respirator, cl ies der d as per the condition | ith skin and eyes. and heavy rubber gloves. Sweep ash spill site after material picku hemical-resistant gloves, safety g | goggles, other protective clothing | |





| Section 12 | Ecological Information | | | |
|------------|--|--|--|--|
| | Data not available | | | |
| Section 13 | Disposal Considerations | | | |
| | On completion of work all used or unusable preparations of this product and derivatives thereof are to be disposed off by autoclaving and/or by incineration. Dispose off waste in accordance with all applicable Federal, State and local laws. | | | |
| Section 14 | Transport Information | | | |
| | UN No. : Not applicable. | | | |
| Section 15 | Regulatory Information | | | |
| | Risk Phrases : Irritating to eyes, respiratory system and skin | | | |
| | Safety Phrases: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice | | | |
| | Safety Phrases : Wear suitable protective clothing | | | |
| | Significance of signs : This symbol designates substances which may have an irritant effect on skin, eyes and respiratory organs. | | | |
| Section 16 | Other Information | | | |
| | The information contained in this data sheet represents the best information currently available to us. However, no warranty is made with respect to its completeness and we assume no liability resulting from its use. The information is offered solely for user's obligation to investigate and determine the suitability of the information for their particular purpose. | | | |