Dehydrated Culture Media Bases / Media Supplements

Material Safety Data Sheet

Code No.	Product	Enriched Thioglycollate DM1738	e Broth		
Section 1	: Chemical Identification Code No. Name of the Product	: DM1738 : Enriched Thioglycollate			
Castion 2	Produced by	: Central Drug House Pv			
	Address : 7/28 Vardaan House, Darya Ganj, New Delhi (INDIA)				
	Tel. No.	: 00 91 11 49404040	to our alternation	Ourse littles	
Section 2	Composition Ingredients	Grams/Litre	Ingredients	Grams/Litre	
	Casein enzymic hydrolysate	17.00	Papaic digest of soyabean meal	3.00	
	Dextrose	6.00	Sodium chloride	2.50	
	*Sodium thioglycollate	0.50	L-Cystine	0.25	
	*Sodium sulphite	0.10	Hemin	0.005	
	Vitamin K1	0.001	Agar	0.70	
	Final pH (at 25°C)	7.0±0.2			
	* Harmful material	,			
	Sodium thioglycollate				
	CAS No. : 367-51-1				
	R : 22-36/37/38 S : 26-36				
	RTECS : AI 7700000				
	Sodium sulphite				
	CAS No. : 7757-83-7				
	R:22-31-36/38 S:26-36/37				
Skin irritation	RTECS : WE 2150000				
Section 3	Hazards Identification				
	Hazard : Inhalation and ingestion of, or skin penetration by these substances is harmful to one's health.Non-recurring,				
Skin irritation	recurring or lengthy exposure to these substances may result in irreversible damage. Caution : Avoid contact with the human body, including inhalation of the vapours and in cases of malaise consult a doctor.				
Section 4	First - Aid Measures	ie naman body, melading mila			
	In case of swallowing wash ou				
	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was	5 minutes. Remove contamin call physician. In case of conta	person is conscious. In case of skin con ated clothing and shoes. In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call	lation, remove to fresh aints of water for at least 1	
Section 5	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label.	5 minutes. Remove contamin call physician. In case of conta	ated clothing and shoes. In case of inha act with eyes, wash with copious amour	lation, remove to fresh aints of water for at least 1	
Section 5	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids	ated clothing and shoes. In case of inha act with eyes, wash with copious amour	lation, remove to fresh aints of water for at least 1	
Section 5	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spo	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray.	ated clothing and shoes.In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call	lation, remove to fresh a nts of water for at least 1 a physician, show the	
Section 5	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S	ated clothing and shoes. In case of inha act with eyes, wash with copious amoun with fingers. In serious conditions, call special fire-fighting procedures. Wear se	lation, remove to fresh aints of water for at least 1 a physician, show the	
	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spo	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk	ated clothing and shoes. In case of inha act with eyes, wash with copious amoun with fingers. In serious conditions, call special fire-fighting procedures. Wear se	lation, remove to fresh aints of water for at least 1 a physician, show the	
	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l	ated clothing and shoes. In case of inha act with eyes, wash with copious amoun with fingers. In serious conditions, call special fire-fighting procedures. Wear se	lation, remove to fresh ai hts of water for at least 1 a physician, show the elfcontained breathing	
Section 6	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l	ated clothing and shoes. In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so kin and eyes.	lation, remove to fresh aints of water for at least 1 a physician, show the elfcontained breathing	
Section 6	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l	ated clothing and shoes. In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so kin and eyes.	lation, remove to fresh a hts of water for at least 1 a physician, show the elfcontained breathing	
Section 6 Section 7	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C	5 minutes. Remove contamin call physician. In case of conta- hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l intilate area and wash spill site	ated clothing and shoes. In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so kin and eyes.	lation, remove to fresh aints of water for at least 1 a physician, show the elfcontained breathing	
Section 6 Section 7	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8	5 minutes. Remove contamin call physician. In case of conta- hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l intilate area and wash spill site	ated clothing and shoes. In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so kin and eyes.	lation, remove to fresh a hts of water for at least 1 a physician, show the elfcontained breathing	
Section 6 Section 7	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sl es ty goggles, rubber boots and l intilate area and wash spill site al Protection	ated clothing and shoes. In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so kin and eyes.	lation, remove to fresh aints of water for at least 1 a physician, show the elfcontained breathing h a bag and hold for wast	
Section 6 Section 7 Section 8	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSH/MSH	5 minutes. Remove contamin call physician. In case of conta- hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and I entilate area and wash spill site al Protection A-approved respirator, chemi	ated clothing and shoes.In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so in and eyes. heavy rubber gloves. Sweep up, place in e after material pickup is complete.	lation, remove to fresh ai nts of water for at least 1 a physician, show the elfcontained breathing n a bag and hold for wast	
Section 6 Section 7 Section 8	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSH/MSH Mechanical exhaust required.	5 minutes. Remove contamin call physician. In case of conta- hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l entilate area and wash spill site al Protection A-approved respirator, chemi erties	ated clothing and shoes.In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so in and eyes. heavy rubber gloves. Sweep up, place in e after material pickup is complete.	lation, remove to fresh aints of water for at least 1 a physician, show the elfcontained breathing h a bag and hold for wast	
Section 6 Section 7 Section 8	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSH/MSH Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous po Colour : Light yellow	5 minutes. Remove contamin call physician. In case of conta- hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l entilate area and wash spill site al Protection A-approved respirator, chemi erties	ated clothing and shoes.In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so in and eyes. heavy rubber gloves. Sweep up, place in e after material pickup is complete.	lation, remove to fresh ai nts of water for at least 1 a physician, show the elfcontained breathing n a bag and hold for wast	
Section 6 Section 7 Section 8 Section 9	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSH/MSH Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous po	5 minutes. Remove contamin call physician. In case of conta- hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with sk es ty goggles, rubber boots and l entilate area and wash spill site al Protection A-approved respirator, chemi erties	ated clothing and shoes.In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so in and eyes. heavy rubber gloves. Sweep up, place in e after material pickup is complete.	lation, remove to fresh aints of water for at least 1 a physician, show the elfcontained breathing h a bag and hold for wast	
Section 5 Section 6 Section 7 Section 8 Section 9 Section 10	amounts of water for at least 1 If breathing becomes difficult, minutes. Assure adequate was container or label. Fire Fighting Measures Extinguishing Media. Water spi Carbon dioxide, dry chemical p apparatus and protective cloth Accidental Release Measure Wear respirator, chemical safe disposal. Avoid raising dust. Ve Handling and Storage Handling - Refer to Section 8 Storage - Store below 30°C Exposure Controls / Person Wear appropriate NIOSH/MSH Mechanical exhaust required. Physical and Chemical Prop Appearance : Homogeneous per Colour : Light yellow Stability and Reactivity	5 minutes. Remove contamin call physician. In case of conta hing by separating the eyelids ray. owder or appropriate foam. S ing to prevent contact with skes ty goggles, rubber boots and l entilate area and wash spill site al Protection A-approved respirator, chemi erties bwder ored as per the conditions spe 5°C. light.	ated clothing and shoes.In case of inha act with eyes, wash with copious amour with fingers. In serious conditions, call special fire-fighting procedures. Wear so in and eyes. heavy rubber gloves. Sweep up, place in e after material pickup is complete.	lation, remove to fresh aints of water for at least 1 a physician, show the elfcontained breathing h a bag and hold for wast er protective clothing.	



Material Safety Data Sheet

	Acute Effects : May be harmful if swallowed.			
	Exposure can cause : Stomach pains, vomiting, diarrhoea. Prolonged or repeated exposure may cause allergic reactions in			
	certain sensitive individuals.			
	RTECS No. : AI 7700000 WE 2150000 For complete information RTECS may be referred.			
Section 12	Ecological Information			
	Data not available			
Section 13	Disposal Considerations			
	On completion of work all used or unusable preparations of this product and derivatives thereof are to be disposed off by			
	autoclaving and/or by incineration. Dispose off waste in accordance with all applicable Federal, State and local laws.			
Section 14	Transport Information			
	UN No. : Not applicable.			
Section 15	Regulatory Information			
	Risk Phrases : Harmful if swallowed			
	Risk Phrases : Irritating to eyes, respiratory system and skin			
	Risk Phrases : Contact with acids liberates toxic gas			
	Risk Phrases : Irritating to eyes and skin			
	Safety Phrases : In case of contact with eyes, rinse immediately with plenty of water and seek medical advice			
	Safety Phrases: Wear suitable protective clothing			
\wedge	Safety Phrases: Wear suitable protective clothing and gloves			
	Significance of signs : Inhalation and ingestion of, or skin penetration by these substances is harmful to one's health. Non-			
	recurring, recurring or lengthy exposure to these substances may result in irreversible damage.			
Skin irritation				
Section 16	Other Information			
	The information contained in this data sheet represents the best information currently available to us. However, no warranty is made with respect to its completeness and we assume no liability resulting from its use. The information is offered solely for user's obligation to investigate and determine the suitability of the information for their particular purpose.			