



Product Specification

cdhfinechemical.com

IMDG Code: 3/III

: 1120

UN No.

n- BUTANOL FOR HPLC & SPECTROSCOPY				
PRODUCT CODE	709700			
SYNONYMS	n-butyl alcohol			
C.I. NO.	N/A			
CASR NO.	71-36-3			
ATOMIC OR MOLECULAR FORMULA	(CH₃)(CH₂)₃OH		\	
ATOMIC OR MOLECULAR WEIGHT	74.12	H ₃ C ~	OH	
PROPERTIES	_			
PARAMETER	LIMIT			
Description	A clear & colourless liquid.	A clear & colourless liquid.		
Solubility	Miscible with absolute industrial methylated spirit (methanol) forming clear &colourless solution.			
Minimum assay (By GC)	99.7%			
Wt. per ml at 20°C	0.808 - 0.810 g	0.808 - 0.810 g		
Refractive index (n) _D ²⁰	1.399-1.400			
Boiling range	116-118°C			
MAXIMUM LIMIT OF IMPURITIES				
Water	0.1%			
Acidity (CH₃COOH)	0.002%			
Non volatile matter	0.001%			
Maximum absorbance in a 1.0 cm cell at :				
215 nm (UV CUT OFF)	1.0			
240 nm	0.1			
275 nm Note(s): Assay (if applicable) method menti	0.01			

Note(s): Assay (if applicable) method mentioned.

HAZARD DANGER Catches fire spontaneously if exposed to air. May be corrosive to metals. Harmful if swallowed. Causes severe skin burns and eye damage. Causes serious eye damage.

PRECAUTIONARY STATEMENTS

Prevention: Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Do not allow contact with air. Keep only in original container. Do not breathe dust/fume/gas/mist/vapours/spray. Wash ... thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection.

Response: IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. Rinse mouth. Brush off loose particles from skin. Immerse in cool water/wrap in wet bandages. Wash contaminated clothing before reuse. Absorb spillage to prevent material damage. Disposal: Dissolve the chemical in dilute acid and neutralize the excess acid with sodium carbonate and run to the normal waste with large amount of water. Any sand used to cover spillage should be thoroughly washed with water beforedisposal as normal waste. Alternatively the neutralized solution can be put in a container and disposed off.

Disposal: Dissolve the chemical in dilute acid and neutralize the excess acid with sodium carbonate and run to the normal waste with large amount of water .Any sand used to cover spillage should be thoroughly washed with water beforedisposal as normal waste. Alternatively the neutralized solution can be put in a container and disposed off.





Product Specification

cdhfinechemical.com

Hazard pictogram(s):







Replace date:- 29-March-2018