

# Central Drug House (P) Ltd.

AN ISO 9001:2008 CERTIFIED COMPANY

IMDG Code: 3/II

: 2398

: 3

UN No.

IATA

Manufacturers of : Laboratory Fine Chemicals & Dehydrated Culture Media www.cdhfinechemical.com

## **Product Specification**

### TERT-BUTYL METHYL ETHER FOR PESTICIDE RESIDUE TRACE

PRODUCT CODE712950SYNONYMSN/AC.I. NO.N/ACASR NO.(1634-04-4)ATOMIC OR MOLECULAR FORMULA $C_5H_{12}O$ ATOMIC OR MOLECULAR WEIGHT88.15

PROPERTIES Unstable in acid solution.

### C5H12O

PARAMETER LIMIT

Description A Clear & colourless liquid.

Solubility Miscible with water.

Minimum assay (By GC) 99.8%

Wt per ml at 20°C About 0.740 g

About 1.3690 Refractive index (n)<sub>p</sub><sup>20</sup>

#### **MAXIMUM LIMIT OF IMPURITIES**

Water 0.05%

Non volatile matter 0.0005%

No impurities present which would show greater signals than 5 pg/ml of Lindance in the Suitable for residue analysis

60/ECD retention range of alpha BHC TO 4.4 DDT

GC/ECD retention range of alpha BHC TO 4,4 DDT

Note(s): Assay (if applicable) method mentioned.

**HAZARD STATEMETNS**: May cause respiratory irritation. Highly flammable liquid and vapor. Causes skin irritation. Causes eye irritation.

PRECAUTIONARY STATEMENTS:

DANGER

**Prevention:** Use only non-sparking tools. Take precautionary measures against static discharge Ground/bond container and receiving equipment. Wash thoroughly after handling. Wash hands thoroughly after handling. Keep away from heat/sparks/open flame - No smoking. Keep container tightly closed. Use explosion-proof electrical/ventilating/lighting/equipment. Wear protective gloves and eye/face protection.

Response: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. If eye irritation persists, get medical advice/attention. If skin irritation occurs, seek medical advice/attention. IF ON SKIN: Gently wash with plenty of soap and water. If on skin or hair:remove/take off immediately all contaminated clothing. Rinse with water/shower. In case of fire, use foam for extinction. Wash/Decontaminate removed clothing before reuse. Remove/Take off immediately all contaminated clothing.

**Disposal**: Dissolve the chemical to be disposed, in water and allow it to run to waste, diluting with large quantities of water.

Hazard Pictogram(s):





Skin irritation \_\_Flammable liquids