



# Product Specification

cdhfinechemical.com

## ACETIC ACID 90% AR

<b>PRODUCT CODE</b>	800334
<b>SYNONYMS</b>	--
<b>C.I. NO.</b>	--
<b>CASR NO.</b>	--
<b>ATOMIC OR MOLECULAR FORMULA</b>	--
<b>ATOMIC OR MOLECULAR WEIGHT</b>	--
<b>PROPERTIES</b>	--

<b>PARAMETER</b>	<b>LIMIT</b>
Description	Clear colourless liquid.
Solubility	Miscible with water.
Assay (Alkalimetric)	89.0 - 91.0% w/w

<b>MAXIMUM LIMIT OF IMPURITIES</b>	
Colour	10 APHA
Iron (Fe)	0.00002%

**Note(s) : Assay (if applicable) method mentioned.**

<b>DANGER</b> <b>Note(s) : Assay (if applicable) method mentioned.</b> <b>HAZARD STATEMENTS :</b> Flammable liquid and vapour. Harmful in contact with skin. Harmful if inhaled. May be harmful if swallowed. May be corrosive to metals. Causes severe skin burns and eye damage. . Causes serious eye damage. Harmful to aquatic life. <b>PRECAUTIONARY STATEMENTS :</b> <b>Prevention :</b> Keep away from heat/sparks/open flames/hot surfaces. – No smoking. Keep container tightly closed. Keep only in original container. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Do not breathe dust/fume/gas/mist/vapours/spray. Avoid breathing dust/fume/gas/mist/vapours/spray. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Wear protective gloves/protective clothing/eye protection/face protection. <b>Response :</b> IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN: Wash with plenty of soap and water. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. Call a POISON CENTER or doctor/physician if you feel unwell. Wash contaminated clothing before reuse. Absorb spillage to prevent material damage. <b>Disposal :</b> Add in small quantities to large, stirred excess of water, keeping the final concentration less than 2%. Neutralize with 5% sodium hydroxide soln. and run to waste with large quantities of running water	IMDG Code : 8/II UN No. : 2789 ATA : 8
--	--

Hazard pictogram(s) :



GHS02

GHS05