



Product Specification

cdhfinechemical.com

KEROSENE (LOW ODOUR)		
PRODUCT CODE	131215	
SYNONYMS	Petroleum ether.	
C.I. NO.		
CASR NO.	(8008-20-6)	
ATOMIC OR MOLECULAR FORMULA		
ATOMIC OR MOLECULAR WEIGHT		
PROPERTIES	-	
PARAMETER	LIMIT	
Description	A clear colourless liquid.	
Solubility	Immiscible with water.	
Density (at 15 ⁰ C)	0.7885 – 0.8100 g	
Refractive index $(n)_{D}^{20}$	1.430 – 1.450	
MAXIMUM LIMIT OF IMPURITIES		
Moisture	0.1%	
Aromatic substance	0.2%	
Note(s) : Assay (if applicable) method mentio	oned.	
DANGER Hazard statements : Harmful if swallowed. Harmful if inhaled. May cause allergic orasthmatic symptoms or breathing difficulties if inhaled. May cause allergic skin reaction. May cause genetic defects. May cause cancer by inhalation. May damage the unbornchild. Causes damage to organs through prolonged or repeated exposure byinhalation. Very toxic to aquatic life. Very toxic to aquatic life with long lasting effects.IMDG Code :3/IIIPrecautionary statements Prevention: Obtain special instructions before use. Do not handle until all safetyprecautions have been read and understood. Do not breath dust/fume/gas/mist/vapours/spray. Avoid breathing dust/fume/gas/mist/ vapours/spray. Wash thoroughlyafter handling. Do not eat, drink or smoke when using this product. Use only outdoorsor in a well-ventilated area. Contaminated work clothing should not be allowed out ofthe workplace. Avoid release to the environment. Wear protective gloves/protectiveclothing/ eye rotection/face protection. Response: IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. IF ON SKIN: Wash with plenty of soap and water. IF INHALED: Remove to fresh air and keep at rest in a position comfortable forbreathing. IF INHALED: If breathing is difficult, remove to fresh air and keep at rest in a position comfortable forbreathing. IF exposed or concerned: Get medical advice/ attention. Call a POISON CENTER or doctor/physician if you feel unwell. If skin irritation or rash occurs: Get medical advice/attention if you feel unwell. In skin irritation or rash occurs: Get medical advice/attention if you feel unwell. Is a POISON CENTER or doctor/physician. Washcontaminated clothing before reuse. Collect spillage.IMDG Code :3/IIIUN No.:1223INTA:3		
than 10g should be dissolved in water and transferred to heavy metal waste drums for collection by specialist disposal company. Hazard Pictogram(s) :- GHS07 GHS08 GHS08 GHS08		

Replace Date 01/07/2020