



## **Product Specification**

cdhfinechemical.com

1,2-PROPANEDIOL AR			
PRODUCT CODE	617585		
SYNONYMS	Propylene glycol		
C.I. NO.	N/A		
CASR NO.	57-55-6		
ATOMIC OR MOLECULAR FORMULA	C <sub>3</sub> H <sub>8</sub> O <sub>2</sub>	$\cap$ H	
ATOMIC OR MOLECULAR WEIGHT	76.10	Ϋ́Π	
PROPERTIES	Under ordinary conditions propylene glycol is stable, but at high tempratures it tends to oxidize giving rist to products such aspropionaldehyde, lactic acid, pyruvic acid & acetic acid. Combustible.	³C ✓ OH	
PARAMETER	LIMIT		
Description	Clear, colourless viscous liquid. Absorbs moisture from moist air.	Clear, colourless viscous liquid. Absorbs moisture from moist air.	
Solubility	10% aqueous solution is clear.		
Appearance of solution	Passes test	Passes test	
Identification test	Passes test		
Identification (By FTIR)	Conforms		
Minimum assay (By GC)	99.5%		
Wt. per ml at 20°C	1.035 - 1.037 g		
Refractive Index (n) $)_D^{20}$	1.431-1.433		
Boiling Range	184-189°C		
MAXIMUM LIMIT OF IMPURITIES			
Water	0.2% 0.007%		
Sulphated ash Free acid (CH₃COOH)	0.007%		
Chloride (CI)	0.007%		
Sulphate (SO <sub>4</sub> )	0.006%		
Heavy metals (Pb)	0.0005%		
Oxidizing substances	Passes test		
Reducing substances	Passes test		
Other glycol (Ethylene glycol)	Passes test		
Note(s): Assay (if applicable) method me	ntioned.		
WARNING		IMDG Code :	
•	ess or dizziness. Causes mild skinirritation. Causes eye irritation. May caus		
allergic skin reaction. PRECAUTIONARY STATEMENTS:		IATA :	
	/mist/vapours/spray. Washthoroughly after handling. Use only outdoors	or	
	colothing should not be allowed out of the workplace. Wear protective		
gloves/protective clothing/eye protection/fa			
	soap and water. IF INHALED:Remove to fresh air and keep at rest in a		
position comfortable for breatning. IF INEYE	S: Rinse cautiously with water for several minutes. Remove contact lense:	5,	

Disposal: Dissolve the chemical to be disposed, in water and allow it to run towaste, diluting with large quantities of water. The chemical should be

ifpresent and easy to do. Continue rinsing. Call a POISON CENTER ordoctor/physician if you feel unwell. If skin irritation occurs: Get medical advice/attention. If skin irritation or rash occurs: Get medical advice/attention. If eyeirritation

mixed withcombustible solvent and burnt in a chemical incinerator equipped with burner and scubber.

persists: Get medical advice/attention. Wash contaminated clothing before reuse.





## **Product Specification**

cdhfinechemical.com

Hazard Pictogram(s) :--



Replace Date 29-Nov-2025