



Product Specification

cdhfinechemical.com

D.P.X. MOUNTANT FOR MICROSCOPY & HISTOLOGY		
PRODUCT CODE	080415	
SYNONYMS	N/A	
С.І. NO.	N/A	
CASR NO.		
ATOMIC OR MOLECULAR FORMULA		
ATOMIC OR MOLECULAR WEIGHT		
PROPERTIES		
PARAMETER	LIMIT	
Description	Colourless to pale yellow clear viscous liquid.	
Wt per ml at 20°C	About 0.920 g	
Refractive index (n) <u>20</u>	~1.515	
D	1.515	
Suitability	To pass the test.	
Note(s) : Assay (if applicable) method me	ntioned.	
DANGER		IMDG Code : 3/III
	ed and enters airways. May cause respiratory irritation. May cause	UN No. : 1993
	vapour. Harmful in contact with skin. Harmful if inhaled. May be	IATA : 3
	ses serious eye irritation. Suspected of causing cancer. May	
	ng fertility. Toxic to aquatic life with long lasting effects.	
PRECAUTIONARY STATEMENTS :		
container and receiving equipment. Wash hand	se only outdoors or in a well ventilated area. Ground/bond	
	dle until all safety precautions have been read and understood. Use	
	sh thoroughly after handling. Obtain special instructions before use.	
	harge. Keep container tightly closed. Use explosion-proof	
	away from heat/sparks/open flame - No smoking. Wear protective	
gloves and eye/face protection. Use only nonsp		
Response : Wash contaminated clothing before	reuse. IF INHALED: Remove to fresh air and keep at rest in a	
position comfortable for breathing. IF IN EYES: F	Rinse cautiously with water for several minutes. Remove contact	
	ng. If eye irritation persists, get medical advice/attention. If	
exposed or concerned: Get medical attention advice. Wear eye/face protection. IF SWALLOWED: Rinse mouth. Do		
NOT induce vomiting. If skin irritation occurs, seek medical advice/attention. IF SWALLOWED: Call a POISON		
CENTER or doctor/physician if you feel unwell. Call a POISON CENTER or doctor/physician if you feel unwell.		
Specific treatment: refer to Label or MSDS. If on skin or hair: remove/take off immediately all contaminated clothing. Rinse with water/shower. In case of fire, use foam for extinction. Wash/Decontaminate removed clothing		
	ity of soap and water. Remove/Take off immediately all	
contaminated clothing.	ity of soap and water. Removel take on inimediately an	
	mical incinerator equipped with burner and scrubber. If the volumes a	re larger than 500ml and no
	e then transfer the waste chemical to waste solvent drum for collection	
company.		
Hazard Pictogram(s) :		
1	\mathbf{v} \mathbf{v}	
Replace date 30-May-2023	GHS02 GHS07 GHS08	

Replace date 30-May-2023