

Central Drug House (P) Ltd.

AN ISO 9001:2008 CERTIFIED COMPANY

Manufacturers of : Laboratory Fine Chemicals & Dehydrated Culture Media www.cdhfinechemical.com

Product Specification

IODINE SOLUTION 1% W/V

PRODUCT CODE		
	849600	
SYNONYMS		
C.I. NO.		
CASR NO.		
ATOMIC OR MOLECULAR FORMULA		
ATOMIC OR MOLECULAR WEIGHT		
PROPERTIES		
PARAMETER	LIMIT	
Description	Reddish brown coloured solution.	
Solubility	Miscible with water.	
Minimum assay	0.9-1.1%	
Note(s) : Assay (if applicable) method		
WARNING		MDG Code :
HAZARD STATEMENTS : May cause drowsi	ness and dizziness. Causes mild skin irritation. Causes eye irritation. May	JN No. :
-	10	ATA .
cause allergic skin reaction.	IA	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS :	I not be allowed out of the workplace. Avoid breathing	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS :	not be allowed out of the workplace. Avoid breathing	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS : Prevention : Contaminated clothing should dust/fume/gas/mist/vapours/spray. Wash Response : If skin irritation occurs, seek me	l not be allowed out of the workplace. Avoid breathing hands thoroughly after Handling . edical advice/attention. If skin irritation or rash occurs, seek medical	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS : Prevention : Contaminated clothing should dust/fume/gas/mist/vapours/spray. Wash Response : If skin irritation occurs, seek me advice/attention. If eye irritation persists, g	I not be allowed out of the workplace. Avoid breathing hands thoroughly after Handling . edical advice/attention. If skin irritation or rash occurs, seek medical get medical advice/attention. IF IN EYES: Rinse cautiously with water for	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS : Prevention : Contaminated clothing should dust/fume/gas/mist/vapours/spray. Wash Response : If skin irritation occurs, seek me advice/attention. If eye irritation persists, g several minutes. Remove contact lenses, if	I not be allowed out of the workplace. Avoid breathing hands thoroughly after Handling . edical advice/attention. If skin irritation or rash occurs, seek medical get medical advice/attention. IF IN EYES: Rinse cautiously with water for present and easy to do. Continue rinsing. Specific treatment: refer to Label	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS : Prevention : Contaminated clothing should dust/fume/gas/mist/vapours/spray. Wash Response : If skin irritation occurs, seek me advice/attention. If eye irritation persists, g several minutes. Remove contact lenses, if or MSDS. IF ON SKIN: Gently wash with plet	I not be allowed out of the workplace. Avoid breathing hands thoroughly after Handling . edical advice/attention. If skin irritation or rash occurs, seek medical get medical advice/attention. IF IN EYES: Rinse cautiously with water for present and easy to do. Continue rinsing. Specific treatment: refer to Label nty of soap and water. Wash contaminated clothing before reuse.	ATA :
cause allergic skin reaction. PRECAUTIONARY STATEMENTS : Prevention : Contaminated clothing should dust/fume/gas/mist/vapours/spray. Wash Response : If skin irritation occurs, seek me advice/attention. If eye irritation persists, g several minutes. Remove contact lenses, if or MSDS. IF ON SKIN: Gently wash with pley Disposal : Dissolve the chemical to be dispo	I not be allowed out of the workplace. Avoid breathing hands thoroughly after Handling . edical advice/attention. If skin irritation or rash occurs, seek medical get medical advice/attention. IF IN EYES: Rinse cautiously with water for present and easy to do. Continue rinsing. Specific treatment: refer to Label	ATA :

Skin irritation