



Product Specification

ZN ACID FAST STAINS KIT

| | |
|-----------------------------|--------|
| PRODUCT CODE | 909810 |
| SYNONYMS | -- |
| C.I. NO. | -- |
| CASR NO. | -- |
| ATOMIC OR MOLECULAR FORMULA | -- |
| ATOMIC OR MOLECULAR WEIGHT | -- |
| PROPERTIES | -- |

COMPOSITION

Carbol fuchsin staining solution strong (814900)

Ingredients

| | |
|-------------------|----------|
| Basic fuchsin | 0.300 gm |
| Ethyl alcohol 95% | 10.00 ml |
| Phenol | 5.00 ml |
| Distilled water. | 85.00 ml |

Acid fast decolourizer (801790)

Ingredients

| | |
|--------------------------------|----------|
| Hydrochloric acid concentrated | 3.00 ml |
| Ethyl alcohol 95% | 97.00 ml |

Methylene Blue alkaline (Loeffler's) (865630)

Ingredients

| | |
|-------------------|----------|
| Methylene blue | 0.300 g |
| Ethyl alcohol 95% | 23.00 ml |
| Distilled water | 77.00 ml |

Note(s) : Assay (if applicable) method mentioned.

DANGER

HAZARD STATEMENTS : Highly flammable liquid and vapour. Fatal if swallowed. Toxic if inhaled. Harmful in contact with skin. Causes serious eye irritation. May damage the unborn child. Harmful to aquatic life. **PRECAUTIONARY STATEMENTS :**
Prevention : Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Avoid breathing dust/fume/gas/mist/vapours/spray. Wash thoroughly after handling. Do not eat, drink or smoke when using this product. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Wear protective gloves/protective clothing/eye protection/face protection. Use personal protective equipment as required.

Response : IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician. IF ON SKIN: Wash with plenty of soap and water. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. IF exposed or concerned: Get medical advice/attention. Call a POISON CENTER or doctor/physician. Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth. If eye irritation persists: Get medical advice/attention. Wash contaminated clothing before reuse.

Disposal : Allow to evaporate in safe open area (applicable for small quantities). The chemical should be burnt in a chemical incinerator equipped with burner and scrubber. If the volumes are larger than 500ml and no incinerator and site of evaporation is not available then transfer the waste chemical to waste solvent drum for collection by specialist disposal company.

IMDG Code :

--

UN No. :

--

IATA : --



Central Drug House (P) Ltd.

AN ISO 9001:2008 CERTIFIED COMPANY

Manufacturers of : Laboratory Fine Chemicals & Dehydrated Culture Media

www.cdhfinechemical.com



Acute toxicity Flammable liquids